

SEIMS BRIDGE – NORWAY

This bridge was protected with **ZINGA** in 1991. Since then, not any maintenance was done on this bridge. A major inspection in the summer of 2016 showed that the **25-year-old ZINGA** layers are still protecting the steel very well and will continue to do so for many years to come. At certain places, the protection was quite thin, so it was suggested to add another layer of **ZINGA** on these areas.



These pictures were taken **25 years after exposure**, without any maintenance.

System:

ZINGA

2 x 60 µm DFT